

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
A 000	INITIAL COMMENTS The following represents the findings of the California Department of Public Health during a Complaint Validation Survey from 3/13/2023 to 3/17/2023. Complaint number CA00829585. The census on 3/13/2023 was 75. The total number of patients sampled was 12. Representing the California Department of Public Health: Health Facilities Evaluator Nurse, 39421 Health Facilities Evaluator Nurse, 31794 A0528- 483.26 Radiologic Services- COP was not met.	A 000			
A 528	RADIOLOGIC SERVICES CFR(s): 482.26 The hospital must maintain, or have available, diagnostic radiological services. If therapeutic services are also provided, they, as well as the diagnostic services, must meet professionally approved standards for safety and personnel qualifications. This CONDITION is not met as evidenced by: Based on observation, interview, and available record review the hospital failed to provide radiologic services in a safe manner as evidenced by: 1. Two hospital personnel (one Registered Nurse and one Patient Care Technician) entered Zone III with an Intensive Care Patient (ICU) on a ferromagnetic bed and were left unsupervised by MRI personnel. non-MRI (Magnetic Resonance Imaging) personnel while two staff (one registered Nurse , RN 1 and one Patient Care	A 528	Finding #1 Immediate Actions 1. The Magnetic Resonance Imaging (MRI) suite was placed on lock down after the event, including entrance to Zone IV. MRI magnet was non-operational following the event.		2/23/23

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Shail Colton *SV/AM* *5/16/23*

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #1 (continued) 2. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines (RAD 13.08) of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following: a. MRI Safety Guidelines RAD 13.08 • Align better with American College of Radiology (ACR) Manual on MR Safety 2020. • Include additional MRI safety measures and workflows to ensure patient and staff safety. • Include Magnetic Resonance Medical Director (MRMD), Magnetic Resonance Safety Officer (MRSO), and Magnetic Resonance Safety Expert (MRSE) roles and responsibilities. b. Staff education and training materials • Add simulation of Rapid Response and Code Blue drills from Zone IV to Zone II, practicing calling for help/getting emergent assistance • Add orientation for non-MRI staff/providers to include safety practices review including MRI Safety Screening Questionnaire occurring in Zone II, gauss line provisions, waiting for direction to enter Zone III or IV from MRI technologist, and non-MRI staff remaining in direct line of sight of MRI staff.	2/23/23	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #1 (continued) 3. Multidisciplinary team consulted with Clinical Technology and General Electric (GE) to confirm environmental safety of MRI area. a. Clinical Technologists and facility Engineers evaluated the MRI machine initially to verify environmental safety, including ensuring appropriate oxygen levels, validating absence of helium, confirming magnet quenching, guaranteeing safe removal of the hospital bed, and allowing the magnet to defrost. • Facility Engineers assessed the oxygen sensing device in Zone IV and noted that it was not triggered during the event which indicated that appropriate oxygen level was present. • Clinical Technologist reviewed the magnet monitor logs and noted that, at approximately 8:00 am on the day of the event, the data showed the magnet pressure went from 1.5 psi to 0 psi which coincided with the hospital bed impacting the MRI magnet. Then approximately an hour later at 9:00 am, the helium pressure went from 94% to 0% which indicated the MRI magnet ramped itself down. • Facility Engineers safely removed the hospital bed after verifying the quench of the MRI magnet. b. Clinical Technologists continued the evaluation of the MRI machine to determine the extent of the damage related to the event, including determining the list of parts needed for repair.	2/23/23	2/23/23
					2/24/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #1 (continued) Systemic Actions 1. Kaiser Permanente (KP) Learn (online education system) MRI Safety learning module assigned to all active MRI staff. 2. All active MRI staff were re-educated on the MRI Safety Guidelines policy. The importance of the following safety measures was reviewed and reinforced with staff to ensure patient and staff safety during MRI diagnostic visit. a. Patients and staff must be screened using MRI Safety Screening Questionnaire in Zone II (room 1N96). b. Patients and staff must remain in line of sight or under immediate supervision of a Level 2 MRI personnel, and wanded in Zone III. c. Door to Zone IV must be closed at all times, except when entering or exiting or participating in patient care. In addition, patients must remain in line of sight or under immediate supervision of a Level 2 MRI personnel. 3. Clinical Technology Engineers and GE staff sourced the MRI parts needed for repair. However, Supply Chain shortages led to difficulties in securing the actual parts of the magnet, resulting delay in replacement. a. Clinical Technology Engineer completed MRI corrective service and calibrations, and cleared the MRI magnet for operation. b. Physicist performed a Post Quench System Performance Evaluation and certified that the MRI magnet passed. c. The MRI machine is scheduled to be opened for patient diagnostic imaging.	3/06/23	3/21/23
				4/13/23	4/14/23
				4/17/23	5/30/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #1 (continued) d. The MRI Safety Guidelines policy was updated to include better alignment with the ACR Manual on MR Safety 2020, additional MRI safety measures and workflows, and MRMD, MRSO, and MRSE roles and responsibilities. Moreover, these policy additions were made to directly impact patient safety through heightening awareness of staff safety practices and implementation of these two new patient safety workflows: • MRI Patient Safety Checklist • MRI Safety Stop 4. Reinforce accountability of MRI leadership to review and investigate all near misses and appropriate corrective actions instituted in a timely manner with staff participation. 5. MRI Radiologists to conduct weekly safety rounds with staff. These rounds to include direct observations of staff safety practices, solicit staff feedback, and promote staff engagement. 6. Initial orientation for all new MRI staff to include education on MRI Safety Guidelines, including supervision of non-MRI personnel in Zone III. 7. Part-time/per diem and staff on leave of absence (LOA) to complete the required training prior to participating in patient care duties. Monitoring 1. Monitor completion of active MRI staff re-education regarding MRI Safety Guidelines policy until 100% completion.	5/8/23	5/12/23
				Ongoing	
				Ongoing	
				8/31/23	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #1 (continued) 2. Completion of 30 direct observational audits confirming supervision of non-MRI personnel in Zone III. 3. Monitor completion of MRI Safety Checklist monthly through 30 audits monthly. 4. Completion of 30 monthly direct observational audits for correct use of MRI Safety Stop. 5. Data to be reported monthly to the MRI Safety Committee (MRISC) and Quality Management Committee (QMC) which reports to the Medical Executive Committee (MEC), until the target is met for 4 consecutive months. 6. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	8/31/23 8/31/23 8/31/23 9/30/23 Ongoing	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528 A528	Finding #2 Immediate Actions 1. The MRI suite was placed on lock down after the event, including entrance to Zone IV. MRI magnet was non-operational following the event. 2. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following: a. MRI Safety Guidelines • Align better with ACR Manual on MR Safety 2020. • Include additional MRI safety measures and workflows to ensure patient and staff safety. • Include MRMD, MRSO, and MRSE roles and responsibilities. b. Staff education and training materials • Add simulation of Rapid Response and Code Blue drills from Zone IV to Zone II, practicing calling for help/getting emergent assistance • Add orientation for non-MRI staff/providers to include safety practices review including MRI Safety Screening Questionnaire occurring in Zone II, gauss line provisions, waiting for direction to enter Zone III or IV from MRI technologist, and non-MR staff remaining in direct line of sight of MRI staff.	2/23/23 2/23/23	

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 2 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #2 (continued) 4. Training for active MRI staff was completed on the following: a. Re-education regarding requirement to keep the door to Zone IV closed at all times, with the exception of transporting a patient in and out of Zone IV or when MRI staff are providing patient care within Zone IV. b. All aspects of MRI Safety Guidelines policy are consistently followed, including keeping the door closed to Zone IV c. Completion of MRI Safety Checklist 5. Initial orientation for all new MRI staff to include education on MRI Safety Guidelines, annual online MRI Safety Learning Module and MRI Safety Checklist. 6. Part-time/per diem and staff on leave to be re-educated on MRI Safety Guidelines, annual online MRI Safety Learning Module, and MRI Safety Checklist prior to participating in patient care duties. Monitoring 1. Monitor completion of active MRI staff re-education regarding requirement to keep the door to Zone IV closed at all times, with the exception of transporting a patient in and out of Zone IV or when MRI staff are providing patient care within Zone IV until 100% completion. 2. Completion of 30 direct observational audits monthly confirming door to Zone IV is kept closed with the exception of transporting a patient in and out of Zone IV or when MRI staff are providing patient care within Zone IV.	4/14/23	Ongoing
				Ongoing	
				8/31/23	
				8/31/23	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #2 (continued) 3. Monitor completion of MRI Safety Checklist monthly through 30 audits monthly. 4. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 5. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	8/31/23 9/30/23 Ongoing	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528 A528	Finding #3 Immediate Actions 1. The MRI suite was placed on lock down after the event, including entrance to Zone IV. MRI magnet was non-operational following the event. 2. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following: a. MRI Safety Guidelines • Align better with ACR Manual on MR Safety 2020. • Include additional MRI safety measures and workflows to ensure patient and staff safety. • Include MRMD, MRSO, and MRSE roles and responsibilities. b. Staff education and training materials • Add simulation of Rapid Response and Code Blue drills from Zone IV to Zone II, practicing calling for help/getting emergent assistance • Add orientation for non-MRI staff/providers to include safety practices review including MRI Safety Screening Questionnaire occurring in Zone II, gauss line provisions, waiting for direction to enter Zone III or IV from MRI technologist, and non-MR staff remaining in direct line of sight of MRI staff.	2/23/23 2/23/23	

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 2 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #3 (continued) 4. Clinical Technology checked Ferroguard device at the entrance to Zone IV and confirmed it was functional. 5. Multidisciplinary team rounded in the MRI area within 24 hours of the event to assess staff understanding of Ferroguard device, including the alarm and response to alarms. Systemic Actions 1. All active MRI staff were re-educated on the MRI Safety Guidelines policy. The importance of the following safety measures was reviewed and reinforced with staff to ensure patient and staff safety during MRI diagnostic visit. a. Patients and staff must be screened using MRI Safety Screening Questionnaire in Zone II (room 1N96). b. Patients and staff must remain in line of sight or under immediate supervision of a Level 2 MRI personnel, and wanded in Zone III. c. Door to Zone IV must be closed at all times, except when entering or exiting or participating in patient care. In addition, patients must remain in line of sight or under immediate supervision of a Level 2 MRI personnel. 2. Metrasens Vendor was brought onsite to conduct in-person didactic training and competency assessment for all active MRI staff. 3. Metrasens Vendor performed preventative maintenance on Ferroguard device. absence of ferrous objects.	2/23/23 2/24/23 3/21/23 3/27/23 3/30/23	

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 2 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #3 (continued) Monitoring 1. Completion of 30 direct observational audits monthly for correct use of the Ferrogaurd until 100% compliance. 2. Monitoring of daily and weekly QC logs to ensure completion until 100% compliance. 3. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 4. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	8/31/23 8/31/23 9/30/23 Ongoing	

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 2 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #4 (continued) • Add orientation for non-MRI staff/providers to include safety practices review including MRI Safety Screening Questionnaire occurring in Zone II, gauss line provisions, waiting for direction to enter Zone III or IV from MRI technologist, and non-MRI staff remaining in direct line of sight of MRI staff. Systemic Actions 1. All active MRI staff were re-educated on the MRI Safety Guidelines policy. The importance of the following safety measures was reviewed and reinforced with staff to ensure patient and staff safety during MRI diagnostic visit. a. Patients and staff must be screened using MRI Safety Screening Questionnaire in Zone II (room 1N96). b. Patients and staff must remain in line of sight or under immediate supervision of a Level 2 MRI personnel, and wanded in Zone III. c. Door to Zone IV must be closed at all times, except when entering or exiting or participating in patient care. In addition, patients must remain in line of sight or under immediate supervision of a Level 2 MRI personnel. 2. The MR Safety Guidelines Policy was revised to include that screening of patients and staff would occur in Zone II (room 1N96) prior to entering Zone III. a. Zone II: Controlled access location discussed with MRI Level 2 personnel for consideration of potential/actual risk of scanning.	3/21/23	5/08/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #4 (continued) b. Zone III: Restricted access area where screening of MRI patients and personnel continues and is finalized under supervision by MRI technologists in preparation for entry into Zone IV. • Will complete an MRI Screening Safety Questionnaire before being allowed entrance into Zone III. o Any "yes" answers will be discussed with MRI Level 2 personnel for consideration of potential/actual risk of scanning. • All Non-MRI personnel needing to enter Zone III must first complete an MRI safety questionnaire that has been reviewed by MRI staff before entering Zone III. o Patients and visitors will not be allowed in the MRI area (Zone III and IV) unless escorted and screened by an MR technologist, radiologist, or other trained Level 2 MRI personnel. o All patients having an MRI procedure will complete and sign an MRI Safety Screening form before being allowed into Zone III. o Any question answered "yes" will be investigated and resolved before the patient is allowed into Zone III. 3. Developed an MRI Safety Stop process which includes the following steps: a. Before proceeding to the Zone IV door, confirm the following: absence of ferrous objects and equipment is MRI safe. b. Only enter Zone IV when MRI personnel is present and when instructed to enter.	3/29/23	

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 2 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #4 (continued) Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff		
		A528	Finding #5 Immediate Actions 1. The MRI suite was placed on lock down after the event, including entrance to Zone IV. MRI magnet was non-operational following the event. 2. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following: a. MRI Safety Guidelines • Align better with ACR Manual on MR Safety 2020. • Include additional MRI safety measures and workflows to ensure patient and staff safety. • Include MRMD, MRSO, and MRSE roles and responsibilities.		2/23/23 2/23/23

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #5 (continued) b. Patient and staff to remain in direct line of sight by MRI staff while in Zone III. • Entrance into Zone III is prohibited until accompanied by MRI staff. • Any non-MRI staff will remain in Zone III until directed by MRI staff to complete next steps. c. Safety screening process to be completed for inpatient and staff in Zone III. 4. Created the MRI Safety Checklist as visual aids to ensure all pertinent safety measures are addressed and in place before transporting a patient to MRI and within Zones II, III and IV. All pertinent safety actions, including: a. MRI staff to complete direct visualization as final check for ferrous objects in Zone III. b. MRI staff to review staff and patient screening forms in Zone II. c. Transfer patient on hospital bed to MRI exam table while Zone II. d. Safety reminders reviewed with patient care team including do not enter Zone IV without permission from MRI personnel. e. MRI staff to ensure all steps of MRI Safety Stop are completed. 5. Developed an MRI Safety Stop process which includes the following steps: a. Before proceeding to the Zone IV door, confirm the following: absence of ferrous objects and equipment is MRI safe. b. Only enter Zone IV when MRI personnel is present and when instructed to enter.	4/07/23	3/29/23

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 2 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #5 (continued) 2. Completion of 30 monthly direct observational audits for correct use of revised workflow. 3. Completion of 30 monthly direct observational audits for correct use of MRI Safety Checklist. 4. Completion of 30 monthly direct observational audits for correct use of MRI Safety Stop. 5. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 6. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	8/31/23	
		A528	Finding #6 Immediate Actions 1. The MRI suite was placed on lock down after the event, including entrance to Zone IV. MRI magnet was non-operational following the event. 2. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following: a. MRI Safety Guidelines • Align better with ACR Manual on MR Safety 2020.	2/23/23	2/23/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #6 (continued) • Include additional MRI safety measures and workflows to ensure patient and staff safety. • Include MRMD, MRSO, and MRSE roles and responsibilities. b. Staff education and training materials • Add simulation of Rapid Response and Code Blue drills from Zone IV to Zone II, practicing calling for help/getting emergent assistance • Add orientation for non-MRI staff/providers to include safety practices review including MRI Safety Screening Questionnaire occurring in Zone II, gauss line provisions, waiting for direction to enter Zone III or IV from MRI technologist, and non-MRI staff remaining in direct line of sight of MRI staff. 3. Multidisciplinary team consulted with Clinical Technology and General Electric (GE) to confirm environmental safety of MRI area. a. Clinical Technologists and facility Engineers evaluated the MRI machine initially to verify environmental safety, including ensuring appropriate oxygen levels, validating absence of helium, confirming magnet quenching, guaranteeing safe removal of the hospital bed, and allowing the magnet to defrost. • Facility Engineers assessed the oxygen sensing device in Zone IV and noted that it was not triggered during the event which indicated that appropriate oxygen level was present.	2/23/23	2/23/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #6 (continued) - Clinical Technologist reviewed the magnet monitor logs and noted that, at approximately 8:00 am on the day of the event, the data showed the magnet pressure went from 1.5 psi to 0 psi which coincided with the hospital bed impacting the MRI magnet. Then approximately an hour later at 9:00 am, the helium pressure went from 94% to 0% which indicated the MRI magnet ramped itself down. - Facility Engineers safely removed the hospital bed after verifying the quench of the MRI magnet. - Clinical Technologists continued the evaluation of the MRI machine to determine the extent of the damage related to the event, including determining the list of parts needed for repair. Systemic Actions - All active MRI staff were re-educated on the MRI Safety Guidelines policy. The importance of the following safety measures was reviewed and reinforced with staff to ensure patient and staff safety during MRI diagnostic visit. - Patients and staff must be screened using MRI Safety Screening Questionnaire in Zone II (room 1N96). - Patients and staff must remain in line of sight or under immediate supervision of a Level 2 MRI personnel, and wanded in Zone III. - Door to Zone IV must be closed at all times, except when entering or exiting or participating in patient care. In addition, patients must remain in line of sight or	2/24/23	3/21/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #6 (continued) under immediate supervision of a Level 2 MRI personnel. 2. Development of the MRI Quenching Learning Module to provide increased detail specific to evaluation prior to, evacuation for, activation of, and reporting with quenching of the MRI magnet in progress. a. Module to be assigned to all active MRI technologists for completion. 3. Revised the MRI Safety Guidelines to clarify and provide increased detail specific to evaluation prior to, evacuation for, activation of and reporting with quenching of the MRI magnet. a. Revised policy to be submitted to MEC for approval. b. Training of all active MRI technologists to be completed. 4. Initial orientation for all new MRI technologists to include education on MRI Quenching Learning Module. 5. Part-time/per diem and staff on leave to be educated on the MRI Safety Guidelines and MRI Quenching Learning Module prior to participating in patient care duties. Monitoring 1. Monitor the completion of review of the revised MRI Safety Guidelines by all active MRI staff until 100% of staff have completed review. 2. Monitor the completion of the MRI Quenching learning module by all active MRI technologists with a target of 100%.	5/01/23	5/08/23
				5/08/23	5/15/23
				Ongoing	Ongoing
				Ongoing	8/31/23
					8/31/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #6 (continued) 3. Direct rounding of all active MRI staff to validate knowledge retention related to quenching process using a 5-question interview format with a target passing score of 100%. 4. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 5. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	8/31/23	
		A528	Finding #7 Immediate Actions 1. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following:	9/30/23	Ongoing
				2/23/23	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #7 (continued) a. MRI Safety Guidelines • Align better with ACR Manual on MR Safety 2020. • Include additional MRI safety measures and workflows to ensure patient and staff safety. • Include MRMD, MRSO, and MRSE roles and responsibilities. b. Staff education and training materials • Add simulation of Rapid Response and Code Blue drills from Zone IV to Zone II, practicing calling for help/getting emergent assistance • Add orientation for non-MRI staff/providers to include safety practices review including MRI Safety Screening Questionnaire occurring in Zone II, gauss line provisions, waiting for direction to enter Zone III or IV from MRI technologist, and non-MRI staff remaining in direct line of sight of MRI staff. Systemic Actions 1. MRISC with multidisciplinary membership discussed the roles of MRMD and MRSO per the revised MRI Safety Policy. 2. Revised MRI Safety Guidelines to include definitions and required annual MRI safety training of MRMD and MRSO in accordance with the ACR Manual on MR Safety 2020. Revised policy to be submitted to MEC for approval.	3/29/23	5/08/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #7 (continued) a. MRI safety specific education on annual basis is required for MRMD and MRSO. 3. Communication outlining roles and responsibilities for MRMD and MRSO shared with MRI department Radiologists and staff. 4. All active MRI Radiologists to review revised MRI Safety Guidelines. 5. Initial orientation for newly hired MRMD and MRSO includes review of MRI Safety Guidelines and completion of Level 2 MRI Safety training. Monitoring 1. Monitor completion of MRI Level 2 Safety training and attestation to ensure all active MRI Radiologists' understanding of revised MRI Safety Policy content until 100% completion. 2. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 3. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff		5/31/23 5/31/23 Ongoing 8/31/23 9/30/23 Ongoing
		A528	Finding #8 Immediate Actions		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #8 (continued) 1. The MRI suite was placed on lock down after the event, including entrance to Zone IV. MRI magnet was non-operational following the event. 2. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following: a. MRI Safety Guidelines • Align better with ACR Manual on MR Safety 2020. • Include additional MRI safety measures and workflows to ensure patient and staff safety. • Include MRMD, MRSO, and MRSE roles and responsibilities. b. Staff education and training materials • Add simulation of Rapid Response and Code Blue drills from Zone IV to Zone II, practicing calling for help/getting emergent assistance • Add orientation for non-MRI staff/providers to include safety practices review including MRI Safety Screening Questionnaire occurring in Zone II, gauss line provisions, waiting for direction to enter Zone III or IV from MRI technologist, and non-MRI staff remaining in direct line of sight of MRI staff.	2/23/23 2/23/23	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #8 (continued) Systemic Actions 1. All active MRI staff were re-educated on the MRI Safety Guidelines policy. The importance of the following safety measures was reviewed and reinforced with staff to ensure patient and staff safety during MRI diagnostic visit. a. Patients and staff must be screened using MRI Safety Screening Questionnaire in Zone II (room 1N96). b. Patients and staff must remain in line of sight or under immediate supervision of a Level 2 MRI personnel, and wanded in Zone III. c. Door to Zone IV must be closed at all times, except when entering or exiting or participating in patient care. In addition, patients must remain in line of sight or under immediate supervision of a Level 2 MRI personnel. 2. The MRI Safety Guidelines Policy was revised to include that screening of patients and staff would occur in Zone II (room 1N96) prior to entering Zone III. a. Zone II: Controlled access location in MRI area for patients' screening with MRI Safety Screening Questionnaire and verification of appropriate clothing/gowning, as well as screening of personnel's questionnaire. b. Zone III: Restricted access area where screening of MRI patients and personnel continues and is finalized under supervision by MRI technologists in preparation for entry into Zone IV. • Will complete an MRI Screening Safety Questionnaire before being allowed entrance into Zone III.	3/21/23	5/08/23

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 2 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 1 Assistant, PCT 1) and an one patient (P1) were in the Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located oneither side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench ("in MRI, quenching refers to rapid expulsion of the liquid cryogen used to maintain the MRI magnet in a superconducting state") the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI Safety Guidelines..." and as referenced in the Academy of Radiology MRI Safety Guide as referenced in their policy and procedure for MRI safety Guidelines. 8. The required screening of one patient and two non-MRI personnel was not performed in	A 528	Finding #8 (continued) 5. Initial orientation for all new MRI staff to include education on MRI Guidelines, annual online MRI Safety Learning Module, adherence to proper workflow, MRI Safety Checklist, and MRI Safety Stop. 6. All elements above to be included in the MRI annual competency. 7. Part-time/per diem and staff on leave to be re-educated on MRI Guideline, annual online MRI Safety Learning Module, adherence to revised work and MRI Safety Checklist prior to participating in patient care duties. Monitoring 1. Monitor the completion of active MRI staff re-education regarding screening of non-MRI personnel prior to entering Zone III until 100% completion. 2. Completion of 30 direct observational audits monthly for correct use of screening of non-MRI personnel prior to entering Zone III utilizing the MRI Safety Checklist. 3. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 4. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	Ongoing	Ongoing
				8/31/23	8/31/23
				9/30/23	Ongoing

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 2 accordance with the hospital's policy and procedure titled "MRI Safety Guidelines..." 9. The hospital did not have a patient interview/clinical screening area that provided privacy for patient's and non-MR personnel. Zone II (where screening of patient's and non-MR personnel takes place and provides an intermediary space or buffer between Zone I (general public area) and the more strictly controlled MRI zones III(area outside of the magnet room; restricted to only trained MR personnel who have successfully screened patients and non-MR personnel) and Zone IV (where the scanner/magnet is located). The facilities Zone II was located in a hallway used as a pathway by people entering the Radiology Department leading to other Radiologic services. (see hospital physical layout/Radiology Department) (refer to A-0535) The hospital did not provide evidence of the MRMD/MRSO MR safety annual education or Level II MR safety training and did not provide the credential file for the MRMD/MRSO as requested. During an interview with the Imaging Director and the Assistant Medical Group Administrator on 3/13/23 at 13:30 stated that the MRMD was the Chief of Radiology. When queried about the appropriate training for the MRMD, the responsible person was changed to "two MRMD's." (see org chart for radiology). The Imaging Director indicated an MRMD for musculoskeletal imaging and an MRMD for Neurological imaging. (Refer to A0538). During a review of the Imaging Services Redwood City MRI organizational chart showed the following: "Imaging Svcs Chief, MRI MSK Sub-Chief and Imaging Svcs Asst Chief, Neuro	A 528 A528	Finding #9 Immediate Actions 1. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following: a. MRI Safety Guidelines • Align better with ACR Manual on MR Safety 2020. • Include additional MRI safety measures and workflows to ensure patient and staff safety. • Include MRMD, MRSO, and MRSE roles and responsibilities. b. Staff education and training materials • Need to add simulation of Rapid Response and Code Blue drills from Zone IV to Zone II, practicing calling for help/getting emergent assistance • Add orientation for non-MRI staff/providers to include safety practices review including MRI Safety Screening Questionnaire occurring in Zone II, gauss line provisions, waiting for direction to enter Zone III or IV from MRI technologist, and non-MRI staff remaining in direct line of sight of MRI staff.	2/23/23	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 2 accordance with the hospital's policy and procedure titled "MRI Safety Guidelines..." 9. The hospital did not have a patient interview/clinical screening area that provided privacy for patient's and non-MR personnel. Zone II (where screening of patient's and non-MR personnel takes place and provides an intermediary space or buffer between Zone I (general public area) and the more strictly controlled MRI zones III(area outside of the magnet room; restricted to only trained MR personnel who have successfully screened patients and non-MR personnel) and Zone IV (where the scanner/magnet is located). The facilities Zone II was located in a hallway used as a pathway by people entering the Radiology Department leading to other Radiologic services. (see hospital physical layout/Radiology Department) (refer to A-0535) The hospital did not provide evidence of the MRMD/MRSO MR safety annual education or Level II MR safety training and did not provide the credential file for the MRMD/MRSO as requested. During an interview with the Imaging Director and the Assistant Medical Group Administrator on 3/13/23 at 13:30 stated that the MRMD was the Chief of Radiology. When queried about the appropriate training for the MRMD, the responsible person was changed to "two MRMD's." (see org chart for radiology). The Imaging Director indicated an MRMD for musculoskeletal imaging and an MRMD for Neurological imaging. (Refer to A0538). During a review of the Imaging Services Redwood City MRI organizational chart showed the following: "Imaging Svcs Chief, MRI MSK Sub-Chief and Imaging Svcs Asst Chief, Neuro	A 528	Finding #9 (continued) Systemic Actions 1. Reviewed physical space within the MRI department in relation to workflows and identified additional space (room 1N96) to meet privacy requirements in Zone II. 2. All active MRI staff were re-educated on the MRI Safety Guidelines policy. The importance of the following safety measures was reviewed and reinforced with staff to ensure patient and staff safety during MRI diagnostic visit. a. Patients and staff must be screened using MRI Safety Screening Questionnaire in Zone II (room 1N96). b. Patients and staff must remain in line of sight or under immediate supervision of a Level 2 MRI personnel, and wanded in Zone III. c. Door to Zone IV must be closed at all times, except when entering or exiting or participating in patient care. In addition, patients must remain in line of sight or under immediate supervision of a Level 2 MRI personnel. 3. Evaluated the workflow for patient screening while in Zone II and made amendments to ensure privacy is maintained. The new workflow for hospital patients includes interview/clinical screening in room 1N96. 4. Created MRI Safety Checklist as visual aids to ensure all pertinent safety measures are addressed and in place before transporting a patient to MRI and within Zones II, III and IV. 5. Training on MRI Safety Checklist for active PCS and ancillary staff who transport patients to MRI.	3/13/23 3/21/23 3/29/23 4/07/23 4/30/23	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 2 accordance with the hospital's policy and procedure titled "MRI Safety Guidelines..." 9. The hospital did not have a patient interview/clinical screening area that provided privacy for patient's and non-MR personnel. Zone II (where screening of patient's and non-MR personnel takes place and provides an intermediary space or buffer between Zone I (general public area) and the more strictly controlled MRI zones III(area outside of the magnet room; restricted to only trained MR personnel who have successfully screened patients and non-MR personnel) and Zone IV (where the scanner/magnet is located). The facilities Zone II was located in a hallway used as a pathway by people entering the Radiology Department leading to other Radiologic services. (see hospital physical layout/Radiology Department) (refer to A-0535) The hospital did not provide evidence of the MRMD/MRSO MR safety annual education or Level II MR safety training and did not provide the credential file for the MRMD/MRSO as requested. During an interview with the Imaging Director and the Assistant Medical Group Administrator on 3/13/23 at 13:30 stated that the MRMD was the Chief of Radiology. When queried about the appropriate training for the MRMD, the responsible person was changed to "two MRMD's." (see org chart for radiology). The Imaging Director indicated an MRMD for musculoskeletal imaging and an MRMD for Neurological imaging. (Refer to A0538). During a review of the Imaging Services Redwood City MRI organizational chart showed the following: "Imaging Svcs Chief, MRI MSK Sub-Chief and Imaging Svcs Asst Chief, Neuro	A 528	Finding #9 (continued) 6. Initial orientation for all new MRI staff to include education on the above elements. 7. Part-time/per diem and staff on leave to be educated on the revised workflow, and MRI Safety Checklist prior to participating in patient care duties. Monitoring 1. Completion of 30 monthly direct observation audits for adherence to revised workflow to maintain patient privacy in MRI area until 100% completion. 2. Monitoring completion of MRI Safety Checklist through 30 audits monthly. 3. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 4. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	Ongoing Ongoing 8/31/23 8/31/23 9/30/23 Ongoing	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 528	Continued From page 3 MRI Sub-Chief, CSP Rad Lead. The Imaging Director hand wrote the MRMD/MRSO designations for the Radiologist she was indicating as the two designated MRMD's. (refer to Imaging services org. chart). The Imaging Service Director indicated that one of the Radiologists was the MRMD and the MRSO. During an interview with the Chief of Radiology on 3/15/23 at 14:05, stated that the MRMD received MR safety training in their Residency and Fellowship programs. (Refer to A0538).	A 528			
A 535	The cumulative effect of these systemic problems resulted in the facility's failure to provide care to their patients and hospital personnel in a safe environment. SAFETY POLICY AND PROCEDURES CFR(s): 482.26(b) [§482.26 Condition of Participation: Radiologic Services §. If therapeutic services are also provided, they, as well as the diagnostic services, must meet professionally approved standards for safety and personnel qualifications.] §482.26(b) Standard: Safety for Patients and Personnel The radiologic services, particularly ionizing radiology procedures, must be free from hazards for patients and personnel. This STANDARD is not met as evidenced by: Based on interview and record review, the facility failed to ensure the safety of the patient and staffs when:	A 535			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #1 Immediate Actions 1. The Magnetic Resonance Imaging (MRI) suite was placed on lock down after the event, including entrance to Zone IV. MRI magnet was non-operational following the event. 2. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines (RAD 13.08) of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following: a. MRI Safety Guidelines RAD 13.08 • Align better with American College of Radiology (ACR) Manual on MR Safety 2020. • Include additional MRI safety measures and workflows to ensure patient and staff safety. • Include Magnetic Resonance Medical Director (MRMD), Magnetic Resonance Safety Officer (MRSO), and Magnetic Resonance Safety Expert (MRSE) roles and responsibilities. b. Staff education and training materials • Add simulation of Rapid Response and Code Blue drills from Zone IV to Zone II, practicing calling for help/getting emergent assistance • Add orientation for non-MRI staff/providers to include safety practices review including MRI Safety Screening Questionnaire occurring in Zone II, gauss line provisions, waiting for direction to enter Zone III or IV from MRI	2/23/23	2/23/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #1 (continued) technologist, and non-MRI staff remaining in direct line of sight of MRI staff. 3. Multidisciplinary team consulted with Clinical Technology and General Electric (GE) to confirm environmental safety of MRI area. a. Clinical Technologists and facility Engineers evaluated the MRI machine initially to verify environmental safety, including ensuring appropriate oxygen levels, validating absence of helium, confirming magnet quenching, guaranteeing safe removal of the hospital bed, and allowing the magnet to defrost. • Facility Engineers assessed the oxygen sensing device in Zone IV and noted that it was not triggered during the event which indicated that appropriate oxygen level was present. • Clinical Technologist reviewed the magnet monitor logs and noted that, at approximately 8:00 am on the day of the event, the data showed the magnet pressure went from 1.5 psi to 0 psi which coincided with the hospital bed impacting the MRI magnet. Then approximately an hour later at 9:00 am, the helium pressure went from 94% to 0% which indicated the MRI magnet ramped itself down. • Facility Engineers safely removed the hospital bed after verifying the quench of the MRI magnet. b. Clinical Technologists continued the evaluation of the MRI machine to determine the extent of the damage related to the event, including determining the list of parts needed for repair.	2/23/23	2/23/23
				2/24/23	

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

[illegible]

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #1 (continued) 3. Monitor completion of MRI Safety Checklist monthly through 30 audits monthly. 4. Completion of 30 monthly direct observational audits for correct use of MRI Safety Stop. 5. Data to be reported monthly to the MRI Safety Committee (MRISC) and Quality Management Committee (QMC) which reports to the Medical Executive Committee (MEC), until the target is met for 4 consecutive months. 6. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	8/31/23	8/31/23
				9/30/23	Ongoing

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 5 of 13

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 5 of 13

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 5 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #2 (continued) times, with the exception of transporting a patient in and out of Zone IV or when MRI staff are providing patient care within Zone IV. b. All aspects of MRI Safety Guidelines policy are consistently followed, including keeping the door closed to Zone IV c. Completion of MRI Safety Checklist 5. Initial orientation for all new MRI staff to include education on MRI Safety Guidelines, annual online MRI Safety Learning Module and MRI Safety Checklist. 6. Part-time/per diem and staff on leave to be re-educated on MRI Safety Guidelines, annual online MRI Safety Learning Module, and MRI Safety Checklist prior to participating in patient care duties. Monitoring 1. Monitor completion of active MRI staff re-education regarding requirement to keep the door to Zone IV closed at all times, with the exception of transporting a patient in and out of Zone IV or when MRI staff are providing patient care within Zone IV until 100% completion. 2. Completion of 30 direct observational audits monthly confirming door to Zone IV is kept closed with the exception of transporting a patient in and out of Zone IV or when MRI staff are providing patient care within Zone IV. 3. Monitor completion of MRI Safety Checklist monthly through 30 audits monthly.	Ongoing	Ongoing
				8/31/23	8/31/23
				8/31/23	8/31/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #2 (continued) 4. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 5. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	9/30/23 Ongoing	

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 5 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #3 (continued) gauss line provisions, waiting for direction to enter Zone III or IV from MRI technologist, and non-MRI staff remaining in direct line of sight of MRI staff. 3. Multidisciplinary team consulted with Clinical Technology and GE to confirm environmental safety of MRI area. a. Clinical Technologists and facility Engineers evaluated the MRI machine initially to verify environmental safety, including ensuring appropriate oxygen levels, validating absence of helium, confirming magnet quenching, guaranteeing safe removal of the hospital bed, and allowing the magnet to defrost. • Facility Engineers assessed the oxygen sensing device in Zone IV and noted that it was not triggered during the event which indicated that appropriate oxygen level was present. • Clinical Technologist reviewed the magnet monitor logs and noted that, at approximately 8:00 am on the day of the event, the data showed the magnet pressure went from 1.5 psi to 0 psi which coincided with the hospital bed impacting the MRI magnet. Then approximately an hour later at 9:00 am, the helium pressure went from 94% to 0% which indicated the MRI magnet ramped itself down. • Facility Engineers safely removed the hospital bed after verifying the quench of the MRI magnet.	2/23/23	2/23/23

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 5 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #3 (continued) 3. Metrasens Vendor performed preventative maintenance on Ferrogaurd device. 4. Initiated re-training of all active MRI staff on the workflow of Ferrogaurd and the actions required when an alarm sounds. 5. Training for MRI staff regarding MRI Safety Stop process that includes the following: a. When Ferrogaurd Beacon displays amber or red lights, perform an additional direct visualization/tactile check b. If audible alarm sounds when entering Zone IV, stop and reverify absence of ferrous objects. 6. Training for all MRI staff regarding daily and weekly quality control (QC) according to the manufacturer's instruction for use (MIFU) and record result of pass or fail. a. The Magnetic Resonance Medical Director (MRMD), Magnetic Resonance Safety Officer (MRSO) and the Imaging Services Director are immediately notified of all failures to assess if recalibration of the unit is needed. 7. Demonstration, return-demonstration, and competency assessment of the QC process to be completed by the Imaging Services Director for all other active MRI staff. 8. All elements above to be included in the MRI annual competency. 9. Initial orientation for all new MRI staff to include education on the above elements. 10. Part-time/per diem and staff on LOA to be educated prior to participating in patient care duties.	3/30/23 3/27/23 4/14/23 4/14/23 4/14/23 Ongoing Ongoing Ongoing	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #3 (continued) Monitoring 1. Completion of 30 direct observational audits monthly for correct use of the Ferrogaurd until 100% compliance. 2. Monitoring of daily and weekly QC logs to ensure completion until 100% compliance. 3. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 4. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	8/31/23 8/31/23 9/30/23 Ongoing	

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 5 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #4 (continued) b. Staff education and training materials • Add simulation of Rapid Response and Code Blue drills from Zone IV to Zone II, practicing calling for help/getting emergent assistance • Add orientation for non-MRI staff/providers to include safety practices review including MRI Safety Screening Questionnaire occurring in Zone II, gauss line provisions, waiting for direction to enter Zone III or IV from MRI technologist, and non-MRI staff remaining in direct line of sight of MRI staff. Systemic Actions 1. All active MRI staff were re-educated on the MRI Safety Guidelines policy. The importance of the following safety measures was reviewed and reinforced with staff to ensure patient and staff safety during MRI diagnostic visit. a. Patients and staff must be screened using MRI Safety Screening Questionnaire in Zone II (room 1N96). b. Patients and staff must remain in line of sight or under immediate supervision of a Level 2 MRI personnel, and wanded in Zone III. c. Door to Zone IV must be closed at all times, except when entering or exiting or participating in patient care. In addition, patients must remain in line of sight or under immediate supervision of a Level 2 MRI personnel. 2. The MR Safety Guidelines Policy was revised to include that screening of patients and staff would occur in Zone II (room 1N96) prior to entering Zone III.	03/21/23	5/08/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #4 (continued) a. Zone II: Controlled access location in MRI area for patients' screening with MRI Safety Screening Questionnaire and verification of appropriate clothing/gowning, as well as screening of personnel's questionnaire. b. Zone III: Restricted access area where screening of MRI patients and personnel continues and is finalized under supervision by MRI technologists in preparation for entry into Zone IV. • Will complete an MRI Screening Safety Questionnaire before being allowed entrance into Zone III. o Any "yes" answers will be discussed with MRI Level 2 personnel for consideration of potential/actual risk of scanning. • All Non-MRI personnel needing to enter Zone III must first complete an MRI safety questionnaire that has been reviewed by MRI staff before entering Zone III. o Patients and visitors will not be allowed in the MRI area (Zone III and IV) unless escorted and screened by an MR technologist, radiologist, or other trained Level 2 MRI personnel. o All patients having an MRI procedure will complete and sign an MRI Safety Screening form before being allowed into Zone III. o Any question answered "yes" will be investigated and resolved before the patient is allowed into Zone III. 3. Developed an MRI Safety Stop process which includes the following steps:	3/29/23	

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 5 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #4 (continued) 3. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 4. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	9/30/23	Ongoing
		A535	Finding #5 Immediate Actions 1. The MRI suite was placed on lock down after the event, including entrance to Zone IV. MRI magnet was non-operational following the event. 2. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following: a. MRI Safety Guidelines • Align better with American College of Radiology (ACR) Manual on MR Safety 2020.	2/23/23	2/23/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #5 (continued) • Include additional MRI safety measures and workflows to ensure patient and staff safety. • Include MRMD, MRSO, and MRSE roles and responsibilities. b. Staff education and training materials • Add simulation of Rapid Response and Code Blue drills from Zone IV to Zone II, practicing calling for help/getting emergent assistance • Add orientation for non-MRI staff/providers to include safety practices review including MRI Safety Screening Questionnaire occurring in Zone II, gauss line provisions, waiting for direction to enter Zone III or IV from MRI technologist, and non-MRI staff remaining in direct line of sight of MRI staff. Systemic Actions 1. Reassessment of Zone signage opportunities for improvement by multidisciplinary team. a. Reclassification of designated MRI Safety Zones with improvements in signage identifying different zones per MRI Safety Guidelines. b. Temporary Zone signage posted. c. Replacement permanent signage ordered. 2. Education for MRI staff completed regarding the following: a. Staff/physicians must remain in direct line of sight of an MRI staff member at all times while in Zones III and IV. b. Non-MRI staff are not permitted to enter Zone IV without being first cleared, then escorted by an MRI staff member.	3/13/23 3/29/23 4/05/23 4/11/23 4/07/23	

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 5 of 13

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 5 of 13

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 5 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535			
		A535	Finding #6 Immediate Actions 1. The MRI suite was placed on lock down after the event, including entrance to Zone IV. MRI magnet was non-operational following the event. 2. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following:	2/23/23 2/23/23	

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 5 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #6 (continued) event which indicated that appropriate oxygen level was present. • Clinical Technologist reviewed the magnet monitor logs and noted that, at approximately 8:00 am on the day of the event, the data showed the magnet pressure went from 1.5 psi to 0 psi which coincided with the hospital bed impacting the MRI magnet. Then approximately an hour later at 9:00 am, the helium pressure went from 94% to 0% which indicated the MRI magnet ramped itself down. • Facility Engineers safely removed the hospital bed after verifying the quench of the MRI magnet. b. Clinical Technologists continued the evaluation of the MRI machine to determine the extent of the damage related to the event, including determining the list of parts needed for repair. Systemic Actions 1. All active MRI staff were re-educated on the MRI Safety Guidelines policy. The importance of the following safety measures was reviewed and reinforced with staff to ensure patient and staff safety during MRI diagnostic visit. a. Patients and staff must be screened using MRI Safety Screening Questionnaire in Zone II (room 1N96). b. Patients and staff must remain in line of sight or under immediate supervision of a Level 2 MRI personnel, and wanded in Zone III. c. Door to Zone IV must be closed at all times, except when entering or exiting	2/24/23	3/21/23

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

If continuation sheet Page 5 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #6 (continued) 3. Direct rounding of all active MRI staff to validate knowledge retention related to quenching process using a 5-question interview format with a target passing score of 100%. 4. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 5. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	8/31/23 9/30/23 Ongoing	
		A535	Finding #7 Immediate Actions 1. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following:	2/23/23	

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: SDRL11 Facility ID: CA220000010 If continuation sheet Page 5 of 13

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #7 (continued) 3. Communication outlining roles and responsibilities for MRMD and MRSO shared with MRI department Radiologists and staff. 4. All active MRI Radiologists to review revised MRI Safety Guidelines. 5. Initial orientation for newly hired MRMD and MRSO includes review of MRI Safety Guidelines and completion of Level 2 MRI Safety training. Monitoring 1. Monitor completion of MRI Level 2 Safety training and attestation to ensure all active MRI Radiologists' understanding of revised MRI Safety Policy content until 100% completion. 2. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 3. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	5/31/23 5/31/23 Ongoing 8/31/23 9/30/23 Ongoing	
		A535	Finding #8 Immediate Actions 1. The MRI suite was placed on lock down after the event, including entrance to Zone IV. MRI magnet was	2/23/23	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #8 (continued) non-operational following the event. 2. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following: a. MRI Safety Guidelines • Align better with American College of Radiology (ACR) Manual on MR Safety 2020. • Include additional MRI safety measures and workflows to ensure patient and staff safety. • Include MRMD, MRSO, and MRSE roles and responsibilities. b. Staff education and training materials • Add simulation of Rapid Response and Code Blue drills from Zone IV to Zone II, practicing calling for help/getting emergent assistance • Add orientation for non-MRI staff/providers to include safety practices review including MRI Safety Screening Questionnaire occurring in Zone II, gauss line provisions, waiting for direction to enter Zone III or IV from MRI technologist, and non-MRI staff remaining in direct line of sight of MRI staff. Systemic Actions 1. All active MRI staff were re-educated on the MRI Safety Guidelines policy. The importance of the following safety measures was reviewed and reinforced with staff to ensure patient and staff safety during MRI diagnostic visit.	2/23/23	3/21/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #8 (continued) a. Patients and staff must be screened using MRI Safety Screening Questionnaire in Zone II (room 1N96). b. Patients and staff must remain in line of sight or under immediate supervision of a Level 2 MRI personnel, and wanded in Zone III. c. Door to Zone IV must be closed at all times, except when entering or exiting or participating in patient care. In addition, patients must remain in line of sight or under immediate supervision of a Level 2 MRI personnel. 2. The MRI Safety Guidelines Policy was revised to include that screening of patients and staff would occur in Zone II (room 1N96) prior to entering Zone III. a. Zone II: Controlled access location in MRI area for patients' screening with MRI Safety Screening Questionnaire and verification of appropriate clothing/gowning, as well as screening of personnel's questionnaire. b. Zone III: Restricted access area where screening of MRI patients and personnel continues and is finalized under supervision by MRI technologists in preparation for entry into Zone IV. • Will complete an MRI Screening Safety Questionnaire before being allowed entrance into Zone III. o Any "yes" answers will be discussed with MRI Level 2 personnel for consideration of potential/actual risk of scanning. • All Non-MRI personnel needing to enter Zone III must first complete an MRI safety questionnaire that has been reviewed by MRI staff before entering	5/8/23	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #8 (continued) Zone III. o Patients and visitors will not be allowed in the MRI area (Zone III and IV) unless escorted and screened by an MRI technologist, radiologist, or other trained Level 2 MRI personnel. o All patients having an MRI procedure will complete and sign an MRI Safety Screening form before being allowed into Zone III. o Any question answered "yes" will be investigated and resolved before the patient is allowed into Zone III. 3. Developed an MRI Safety Stop process which includes the following steps: a. Before proceeding to the Zone IV door, confirm the following: absence of ferrous objects and equipment is MRI safe. b. Only enter Zone IV when MRI personnel is present and when instructed to enter. 4. Training for all active MRI staff was completed for: a. Adherence to the revised workflow, including non-MRI staff and patient screening prior to entering Zone III b. MRI Safety Checklist c. MRI Safety Stop 5. Initial orientation for all new MRI staff to include education on MRI Guidelines, annual online MRI Safety Learning Module, adherence to proper workflow, MRI Safety Checklist, and MRI Safety Stop. 6. All elements above to be included in the MRI annual competency.	3/29/23	4/14/23
				Ongoing	Ongoing

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #8 (continued) 7. Part-time/per diem and staff on leave to be re-educated on MRI Guideline, annual online MRI Safety Learning Module, adherence to revised work and MRI Safety Checklist prior to participating in patient care duties. Monitoring 1. Monitor the completion of active MRI staff re-education regarding screening of non-MRI personnel prior to entering Zone III until 100% completion. 2. Completion of 30 direct observational audits monthly for correct use of screening of non-MRI personnel prior to entering Zone III utilizing the MRI Safety Checklist. 3. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 4. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	Ongoing	8/31/23 8/31/23 9/30/23 Ongoing
	interview/clinical screening area (Zone II) that	A535	Finding #9		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #9 (continued) Immediate Actions 1. Multidisciplinary team met to review and evaluate the MRI Safety Guidelines of safety practices in the MRI area, including review of staff education and training materials to identify improvement opportunities. These opportunities included the following: a. MRI Safety Guidelines • Align better with American College of Radiology (ACR) Manual on MR Safety 2020. • Include additional MRI safety measures and workflows to ensure patient and staff safety. • Include MRMD, MRSO, and MRSE roles and responsibilities. b. Staff education and training materials • Add simulation of Rapid Response and Code Blue drills from Zone IV to Zone II, practicing calling for help/getting emergent assistance • Add orientation for non-MRI staff/providers to include safety practices review including MRI Safety Screening Questionnaire occurring in Zone II, gauss line provisions, waiting for direction to enter Zone III or IV from MRI technologist, and non-MRI staff remaining in direct line of sight of MRI staff. Systemic Actions 1. Reviewed physical space within the MRI department in relation to workflows and identified additional space (room 1N96) to meet privacy requirements in Zone II.	2/23/23	3/13/23

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferroguard, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #9 (continued) 2. All active MRI staff were re-educated on the MRI Safety Guidelines policy. The importance of the following safety measures was reviewed and reinforced with staff to ensure patient and staff safety during MRI diagnostic visit. a. Patients and staff must be screened using MRI Safety Screening Questionnaire in Zone II (room 1N96). b. Patients and staff must remain in line of sight or under immediate supervision of a Level 2 MRI personnel, and wanded in Zone III. c. Door to Zone IV must be closed at all times, except when entering or exiting or participating in patient care. In addition, patients must remain in line of sight or under immediate supervision of a Level 2 MRI personnel. 3. Evaluated the workflow for patient screening while in Zone II and made amendments to ensure privacy is maintained. The new workflow for hospital patients includes interview/clinical screening in room 1N96. 4. Created MRI Safety Checklist as visual aids to ensure all pertinent safety measures are addressed and in place before transporting a patient to MRI and within Zones II, III and IV. 5. Training on MRI Safety Checklist for active PCS and ancillary staff who transport patients to MRI. 6. Initial orientation for all new MRI staff to include education on the above elements. 7. Part-time/per diem and staff on leave to be educated on the revised workflow, and MRI Safety Checklist prior to	3/21/23	3/29/23
				4/07/23	4/30/23
				Ongoing	Ongoing

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 4 1. There was no supervision of non-MRI (Magnetic Resonance Imaging) Personnel while two staff (one registered Nurse , RN 1) and one Patient Care Assistant, PCT 1) were in Zone III of the MR area. 2. The entrance door to the Magnetic Room (Zone IV) was left opened. 3. The MRI safety alarm system, (called Ferrogaurd, a wall mounted metal detector that provides a clear, simple, early warning of risk items approaching the magnet room, together with lowest audible alarm rates), located on either side of the entrance to Zone IV (area where the magnet is located) did not function when the hospital bed as pulled through the entrance to Zone IV. 4. The RN, PCT, and patient were not screened prior to entering Zone III, in accordance with the hospitals policy and procedure regarding screening. 5. The RN was level II MR safety trained and continued to move the patient in an ICU bed into Zone IV (area where magnet is located) without stopping in Zone III for a second screening and transferring patient to non-Ferromagnetic bed/table. 6. The MRI technician did not quench the Magnet during an emergency situation in accordance with the hospitals policy and procedure "MRI Safety Guidelines..." 7. The hospital's policy and procedure did not include MRMD and MRSO required MR safety training in their policy and procedure "MRI safety Guidelines..." 8. Required screening of patient and non-MRI personnel was not performed in accordance with the hospital's policy and procedure. 9. The hospital did not have a patient interview/clinical screening area (Zone II) that	A 535	Finding #9 (continued) participating in patient care duties. Monitoring 1. Completion of 30 monthly direct observation audits for adherence to revised workflow to maintain patient privacy in MRI area until 100% completion. 2. Monitoring completion of MRI Safety Checklist through 30 audits monthly. 3. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 4. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	8/31/23 8/31/23 9/30/23 Ongoing	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
A 535	Continued From page 5 would facilitate full and complete patient and personnel disclosure of their medical history. Findings: During an interview with MRI Technologist on 3/13/23 at 13:15 stated that she opened the door to Zone III without first screening the nurse, patient, and patient care technician in Zone II. She indicated she informed the nurse "we're going in head first" and went back to the control room to "open the patient chart." She indicated she left the RN, patient, and PCT alone in Zone III. When queried why she did that, she stated she could not begin the procedure without first opening the chart. The control room is out of the line of sight to Zone III, and indicated she could not begin the procedure without opening the patient chart. When queried about what was priority, the patient or the patient chart, she stated "the patient." While at the computer, she indicated she heard "screaming" and ran out to see the RN pinned against the Magnet by the ICU bed. She did not recall hearing the Ferroguard alarm. During an interview with the MRI Imaging Technician on 3/13/23 at 14:10 stated she had begun a call to another patient when the bell to Zone III rang. She asked the MRI Technologist if she should answer the door or continue with the telephone call. She indicated she was instructed to finish the call and the MRI Technologist would "get the door." The Imaging Technician stated she had just "finished with the call" when she heard screaming coming from outside the control room. She indicated she "did not hear the Ferroguard alarm." She stated the door should not have been left open and the bed should not have been in the	A 535			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 6 doorway. The door to Zone IV should remain closed at all times. -The hospital policy and procedure titled "MRI Safety Guidelines-NCAL Imaging Policy SAS-910 at 5.1.3" indicated "employees, visitors, or staff will not be allowed in the magnet area (Zones III and IV) without the appropriate screening, evaluation, and supervision." MR Level II trained personnel are to be with patients and other non-MR personnel in Zone III at all times. -The hospital policy and procedure titled "MRI Safety Guidelines...5.9.1 indicated "patients and visitors will not be allowed in the MRI area (Zone III & IV) unless escorted and screened by an MRI technologist, radiologist, or other trained Level 2 MRI personnel." -ACR (American College of Radiology) Manual on MR Safety indicated "MR Screening All non-MR personnel needing to enter Zone III must first pass an MR safety screening process...non emergent patients should be MR safety screened at least twice prior to being granted access to the MR environment (Zone III & IV). At least one of these screens should be performed by Level 2 MR personnel verbally and/or interactively. For example, the patient (or their health care proxy) may complete a screening form and subsequently have the responses and contents of that form reviewed together with a Level 2 MR Technologist. -ACR recommendations for conscious, nonemergent patients are to complete written MR safety screening questionnaires prior to entering Zone III. During an interview with the MRI Technologist and MR Imaging Technician on 3/15/23 at 14:00, both concurred that they did not hear the	A 535			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 7 Ferroguard alarm. During a concurrent interview with the Assistant Medical Group administrator and the Director of Imaging Services and record review of the "Ferroguard User Manual," on 3/16/23, both stated that the Ferroguard had not been serviced or maintained since the purchase and installation in 2014. the AMGA stated that the Ferroguard was proprietary and had to serviced by the companies (Metrasens) personnel. The hospital obtained a contract with the company and they will be sending a technician to check the Ferroguard. -According to the Ferroguard User Manual, recommends the following: "approach (observe the Beacon displays when approaching the Ferroguard system) Look (if beacon turns amber or red STOP), Proceed (once the beacon remains green) proceed through the entryway, Listen (if audible alarm sounds as you pass through the Ferroguard, STOP). Three of three interviewed staff (MRI Technologist, Imaging Technician, and PCT) stated they did not hear the Ferroguard alarm during the ICU bed passing through the entryway. -According to the Ferroguard User Manual recommends that annual testing by Metrasens approved Ferroguard technicians, daily qualitative checks, weekly/monthly checks and what to do if a fault is suspected. The facility failed to comply with these recommendations. During an observation in Zone III on 3/13/23 at 11:10, the Ferroguard visual alarm displayed "amber" (indicates detection of moving ferromagnetic material). The audible alarm could not be tested, according to the Imaging Director.	A 535			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 8 During concurrent interviews with the MRI Technologist and Imaging Technician, the patient, RN, and PCT were not screened in Zone II (where written MR safety screening questionnaires are performed) prior to being allowed to Zone III (MRI environment for screened personnel and patients). -The ACR Manual on MR safety indicated "...full stop and final check performed by the MRI technologist is recommended to confirm the satisfactory completion of MR safety screening for the patient, support equipment, and personnel immediately prior to crossing from Zone III to Zone IV. -The hospital policy and procedure "MRI safety Guidelines...5.9.1" indicated "all patients and visitors will not be allowed in the MRI area (Zone III & IV) unless escorted and screened by an MRI technologist, radiologist, or other trained Level II MRI personnel. -The hospital policy and procedure "MRI safety Guidelines...5.9.2 indicated all patients having MRI procedure will complete and sign an MRI safety Screening form before being allowed into Zone III." The patient's initial paper screening was unsigned and was in English, patient was Spanish speaking patient with little to no understanding of English. MRI technologist was supposed to have reviewed the initial screening of all non-MR personnel and the patient prior to allowing them into Zone III. This did not take place. During an interview with the Director of Imaging on 3/14/23 indicated "during procedure the MRI Technologist, was feeling "rushed" because of a timed procedure set for 08:00. Review of the	A 535			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 9 patient schedule did not indicate a timed procedure other than the patient brought to the MRI by the RN and the PCT. When queried whether the MRI technologist should have felt "rushed" or should have focused on patient safety, she stated "patient safety." An interview with the RN was not conducted; nurse did not return request for interviews. The RN was Level II trained (meaning safety for herself, safety for others), despite the Level II training, she proceeded to enter Zone III without any screening and continued to enter Zone IV with a ferromagnetic ICU bed. This failure caused her to be pinned against the magnet by the ICU bed and sustained severe injury to her person, requiring surgical repair of multiple lacerations to her abdomen, mons, and left thigh, as well as removal of two embedded screws. The patient fell to the floor and did not sustain any injuries, the potential for patient severe injury was present. An interview with the MRI Technologist regarding the "quenching" of the magnet, indicated that she did not quench the magnet immediately but had the Clinical Technologist notified to ask if she should do that. The nurse was forcibly removed from the the magnet while still pinned by the ICU bed, review of the nurse's in patient record the treating physician indicated this could have caused more damage to the areas where she sustained lacerations. -The hospital's policy and procedure "MRI Safety Guidelines...5.6.1.13" indicated "staff initiated quench of the magnet only when the object held against the MRI scanner poses an imminent threat of injury or death, such as if a patient or staff member is pinned between the object and	A 535			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 535	Continued From page 10 the magnet..."	A 535			
	An observation and concurrent interview on 3/13/23 at 11:30, Zone II is located in the hallway (pathway to other radiologic services) and offered no privacy for screening and wandering of a patient or non-MRI personnel. The Imaging Director stated the hospital did not have a separate area where MRI patients are screened, change clothing into non-ferromagnetic gowns prior to entering Zone III & IV.				
	The many safety failures by the MRI and non-MRI personnel created a culture of unsafe practices leading to the severe injury of one hospital personnel and the potential for injury to one patient.				
A 538	MONITORING RADIATION EXPOSURE CFR(s): 482.26(b)(3)	A 538	Finding #10 Immediate Actions	3/15/23	
	Radiation workers must be checked periodically, by the use of exposure meters or badge tests, for amount of radiation exposure.		1. Reviewed ACR Manual on MR Safety 2020 guidelines and requirements for MRMD and MRSO.		
	This STANDARD is not met as evidenced by: Based on interview, and record review, the facility failed to provide evidence of the MRMD/MRSO MR safety annual education or Level II MR safety training and did not provide the credential file for the MRMD/MRSO as requested.		Systemic Actions		
	Findings:		1. Completion of required education and training for MRMD and MRSO:		
	During an interview with the Imaging Director and the Assistant Medical Group Administrator on 3/13/23 at 13:30 stated that the MRMD was the Chief of Radiology. When queried about the appropriate training for the MRMD, the responsible person was changed to "two		a. KP Learn Level 2 MRI Safety training	3/29/23	
			b. Board certification by American Board of Radiology	3/01/23	
			c. Annual MRI Safety training course through accredited organization	5/12/23	
			2. MRMD and MRSO appointment and reappointment following the established process through Medical Staff Office.	5/08/23	
			3. MRI Safety Guidelines policy to include MRMD, MRSO roles and responsibilities. Revised policy will be presented to MEC for approval.	5/08/23	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 538	Continued From page 11 MRMD's." (see org chart for radiology). The Imaging Director indicated an MRMD for musculoskeletal imaging and an MRMD for Neurological imaging. During a review of the Imaging Services Redwood City MRI organizational chart showed the following: "Imaging Svcs Chief, MRI MSK Sub-Chief and Imaging Svcs Asst Chief, Neuro MRI Sub-Chief, CSP Rad Lead. The Imaging Director hand wrote the designations under each Radiologist's name to indicate their MRMD/MRSO designations. (refer to Imaging services org. chart). The Imaging Service Director indicated that one of the Radiologists was also the MRSO (Magnetic Resonance Safety Officer). During an interview with the Chief of Radiology on 3/15/23 at 14:05, stated that the MRMD received MR safety training in their Residency and Fellowship programs. -According to the ACR Manual on MR Safety, the MRMD is a licensed physician/radiologist with appropriate training in MR safety. -The facility did not provide the requested documentation showing MR training for the MRMD and did not provide the credential file for Dr. Roberts, MRMD. -According the the ACR Manual on MR safety indicated, "...the responsibility will be assumed by a licensed physician/radiologist with appropriate training in MR safety. MRSO responsibility will be assumed by a suitably trained individual...and all individuals responsible for safety in Zones III or IV of MR environment should be documented as having been successfully educated regarding MR safety issues..." -According to the hospital's policy and procedure	A 538	Finding #10 (continued) Monitoring 1. Monitor MRI physician education until 100% completion. 2. Data to be reported monthly to MRISC and QMC which reports to MEC, until the target is met for 4 consecutive months. 3. For sustainability after reporting target is met, ongoing compliance to be reported quarterly to the MRI leadership, MRISC, QMC, and MEC. Responsible Person/Parties 1. Senior Vice President/Hospital Administrator 2. Chief of Staff	8/31/23	9/30/23
				Ongoing	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2023
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 050541	(X2) MULTIPLE CONSTRUCTION A. BUILDING _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/17/2023
NAME OF PROVIDER OR SUPPLIER KAISER FOUNDATION HOSPITAL - REDWOOD CITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1100 VETERANS BOULEVARD REDWOOD CITY, CA 94063		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
A 538	Continued From page 12 titled "MRI Safety Guidelines-...5.2.1" indicated "basic MRI safety education approved for all appropriate medical center staff employees and advanced MRI safety education for Level 2 MRI personnel will be conducted annually. "	A 538			